

Total number of printed pages—4

53 (IE 401) ELMC

2017

**ELECTRICAL MACHINES**

Paper : IE 401

Full Marks : 100

Time : Three hours

***The figures in the margin indicate full marks for the questions.***

Answer **any five** questions.

1. (a) What is transformer ? Give the concept of ideal transformer. 5
- (b) Derive an expression for the e.m.f. induced in a transformer winding. 5
- (c) A 40kVA transformer with a ratio of 2000/250V has a primary resistance of  $1.15\Omega$  and a secondary resistance of  $0.0155\Omega$ . Calculate (a) the total resistance in terms of the secondary winding (b) the total resistance drop on full load (c) the total copper loss on full load. 10

Contd.

2. (a) Draw neat diagram of a 4-pole dc machine. Label all its parts and mention the material used for each part. 10
- (b) A shunt generator delivers  $50\text{kW}$  at  $250\text{V}$  and  $400\text{rpm}$ . The armature and field resistances are  $0.02\Omega$  and  $50\Omega$  respectively. Calculate the speed of the machine running as a shunt motor and taking  $50\text{kW}$  input at  $250\text{V}$ . Allow  $4\text{V}$  per brush for contact drop. 10
3. (a) Calculate the efficiency at half, full and  $\frac{1}{4}$  load of a  $100\text{kVA}$  transformer for power factor of (a) unity (b)  $0.8$ . The copper loss is  $1000\text{W}$  at full load and the iron loss is  $1000\text{W}$ . 10
- (b) A  $10\text{kW}$ ,  $250\text{V}$ , 8-pole,  $600\text{rpm}$  lap-connected dc generator has 400 armature conductors. At rated voltage and current, armature ohmic losses are  $150\text{ watts}$ . Compute the useful flux per pole. 10
4. (a) Define distribution factor and find its expression for the fundamental frequency. 10

(b) Draw and explain the no-load phasor diagram of a 1-phase transformer. Discuss how primary leakage flux is accounted in the phasor diagram.

5+5=10

5. (a) Explain why a 3-phase induction motor, at no load, operates at a very low power factor. 5

(b) Derive the expression of frequency of rotor winding in case of an induction motor. 5

(c) The power input to a 500V, 50Hz, 6-pole, 3-phase induction motor at 975rpm is 40kW. The stator losses are 1kW. The friction and windage losses total are 2kW. Calculate (a) slip (b) rotor copper loss (c) efficiency. 10

6. (a) Describe one of the various schemes used for exciting synchronous machine. 5

(b) Develop and draw space and time phasor diagrams for a cylindrical-rotor machine in case the alternator operates at an internal power factor of  $\cos\psi$  lagging. 5

(c) A 3-phase, 17.32kVA, 400V, star-connected alternator is delivering rated load at 400V and at 0.8 power factor lag. Its synchronous impedance is  $(0.2 + j2)\Omega$  per phase. Find the load angle at which it is operating. 10

7. (a) Draw the connection diagram, phasor diagram and torque-slip curve of a single phase induction motor. 10

(b) Describe the basic operating principle of the stepper motor. 10